

115 - 20 pm

KCC OIL/GAS REGULATORY OFFICES

Date: 01/30/14 ~2 pm

District: 2

Case #: _____

☐ New Situation

☐ Lease Inspection

☐ Response to Request

☐ Complaint

☐ Follow-Up

☒ Field Report

Operator License No: 30979

API Well Number: _____

Op Name: (b) (6), (b) (7)(C) dba RJ Operating Co.

Spot: SE Sec 24 Twp 20 S Rng 6 ☐ E / ☒ W

Address 1: 1380 24th Ave.

Feet from ☐ N / ☐ S Line of Section

Address 2: _____

Feet from ☐ E / ☐ W Line of Section

City: Galva

GPS: Lat: _____ Long: _____ Date: _____

State: Ks Zip Code: 67443

Lease Name: Matlock SWD Well #: 2

Operator Phone #: (b) (6), (b) (7)

County: Rice

Reason for Investigation:

Check on SWD.

Problem:

Persons Contacted:

Findings:

A truck was backed up by this well -- running in soap, according to the JaCam employee - down the tubing. I walked over by this well, and felt the line coming off the brine tank. It felt like alot of brine was going thru it. This truck was a flat-bed truck with 2 liquid filled caged totes on front and 12 plastic 55 gal. barrels strapped in behind. The JaCam employee said that (b) normally operated the fork-lifts over at the JaCam Plant, and that (b) would come over to this well 1 or 2 times a week. I did not see any hazardous placards placed on the truck.

Action/Recommendations:

Follow Up Required ☐ Yes ☐ No ☐

Date: _____

Tag on truck was a Kansas tag -- RC097 FSR. Truck was a 1 ton long frame, dual-wheeled truck.

Verification Sources:

Photos Taken: yes

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____		

By: (b) (6), (b) (7)

PART II

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 01/30/14

District: 2

License #: 30979

Op Name: 30979

Spot: SE

Sec 24

Twp 20

S Rng 6

☐ E☒ W

County: Rice

Lease Name: Matlock SWD

Well #: 2

I.D. Sign <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/>
<input type="checkbox"/> Tank Battery Condition Condition: <input checked="" type="checkbox"/> Good <input type="checkbox"/> Questionable <input type="checkbox"/> Overflowing	<input type="checkbox"/>
<input type="checkbox"/> Pits, Injection Site Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.	
<input type="checkbox"/> Oil Spill Evidence	
<input type="checkbox"/> Abandoned Well Potential Pollution Problem <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/>
<input type="checkbox"/> Lease Cleanliness <input type="checkbox"/> Very Good <input type="checkbox"/> Satisfactory <input type="checkbox"/> Poor <input type="checkbox"/> Very Bad	<input type="checkbox"/>

Gas Venting <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/>
<input type="checkbox"/> Pits Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.	
<input type="checkbox"/> Saltwater Pipelines Leaks Visible: <input type="checkbox"/> Y <input type="checkbox"/> N Tested for Leaks: <input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Flowing Holes	
<input type="checkbox"/> TA Wells	
<input type="checkbox"/> Monitoring Records	

SWD/ER Injection Well ☐ Yes ☐ No Rice ☐

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections ☐ Yes ☐ No ☐

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status

1-30-'14

RJ. Operating



Matlock-SWD

GW

RC city



2/0